

PIEZAS

A*12PCS



φ15*12MM

B*12PCS



M6*35MM

C*24PCS



φ8*25MM

D*24PCS



M35*15MM

E*8PCS



M6*40MM


F*4PCS




G*4PCS



H*2PCS



I*2PCS



J*16PCS




M6*24MM

K*1PC



L*2PCS



M*4PCS



N*8PCS



O*2PCS



P*2PCS



Q*2PCS



R*4PCS




S*4PCS



T*4PCS



U*1PC



V*16PCS




φ12*12MM



W*28PCS





**ANTES DE EMPEZAR
REVISE EL MATERIAL Y ASEGÚRESE
QUE NO FALTA NADA**




		2610
P1	1PC	1200*600*18MM
P2	1PC	1200*600*18MM
P3	1PC	598*164*18MM
P4	1PC	598*164*18MM
P5	1PC	554*164*18MM
P6	2PCS	164*108*18MM
P7A	1PCS	555*158*18MM
P7B	1PCS	555*158*18MM
P8A	2PCS	232*100*18MM
P8B	2PCS	232*100*18MM
P9	2PCS	494.5*242*18MM
P10	2PCS	520.5*100*18MM







PASO5




PASO6







PASO7




PASO8









PASO13



PASO14





PECES

A*12PCS



φ15*12MM

B*12PCS



M6*35MM

C*24PCS



φ8*25MM

D*24PCS



M35*15MM

E*8PCS



M6*40MM


F*4PCS




G*4PCS



H*2PCS



I*2PCS



J*16PCS




M6*24MM

K*1PC



L*2PCS



M*4PCS



N*8PCS



O*2PCS



P*2PCS



Q*2PCS



R*4PCS



S*4PCS



T*4PCS



U*1PC



V*16PCS




W*28PCS







φ12*12MM

ABANS DE COMENÇAR
 REVISI EL MATERIAL I ASSEGURI'S
 QUE NO FALTA RES




		2610
P1	1PC	1200*600*18MM
P2	1PC	1200*600*18MM
P3	1PC	598*164*18MM
P4	1PC	598*164*18MM
P5	1PC	554*164*18MM
P6	2PCS	164*108*18MM
P7A	1PCS	555*158*18MM
P7B	1PCS	555*158*18MM
P8A	2PCS	232*100*18MM
P8B	2PCS	232*100*18MM
P9	2PCS	494.5*242*18MM
P10	2PCS	520.5*100*18MM







PAS5




PAS6








PAS7



PAS8








galeríasdeltresillo


Experts en relax des de 1970


galeriasdeltresillo.com   

PAS13



PAS14





PART LIST

A*12PCS B*12PCS C*24PCS D*24PCS E*8PCS



φ15*12MM



M6*35MM



φ8*25MM



M35*15MM



M6*40MM


F*4PCS




G*4PCS



H*2PCS



I*2PCS



J*16PCS




M6*24MM

K*1PC



L*2PCS



M*4PCS



N*8PCS



O*2PCS



P*2PCS



Q*2PCS



R*4PCS




S*4PCS



T*4PCS



U*1PC



V*16PCS




W*28PCS







φ12*12MM

CHECK MAKE SURE NOTHING
IS MISSING BEFORE YOU START




		2610
P1	1PC	1200*600*18MM
P2	1PC	1200*600*18MM
P3	1PC	598*164*18MM
P4	1PC	598*164*18MM
P5	1PC	554*164*18MM
P6	2PCS	164*108*18MM
P7A	1PCS	555*158*18MM
P7B	1PCS	555*158*18MM
P8A	2PCS	232*100*18MM
P8B	2PCS	232*100*18MM
P9	2PCS	494.5*242*18MM
P10	2PCS	520.5*100*18MM







STEP5




STEP6







STEP7




STEP8







STEP13



STEP14

